

| Ref. No. | Date      | Time  | Location                   | Measured TSP Level | Unit                         | Action Level | Limit Level | Follow-up action     |   |
|----------|-----------|-------|----------------------------|--------------------|------------------------------|--------------|-------------|----------------------|---|
| X_18A006 | 29-Oct-18 | 16:50 | CMA5b- Pedestrian<br>Plaza | 442.4              | 1hr TSP (ug/m <sup>3</sup> ) | 332.0        | 500         | Possible reason:     | TSP level potentially in relate to the nearby traffic and ambient condition around the monitoring station<br>at the time of monitoring. |
|          |           |       |                            |                    |                              |              |             | Action taken / to be | Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's                                      |
|          |           |       |                            |                    |                              |              |             | taken:               | working procedures.   |
|          |           |       |                            |                    |                              |              |             |                      | No construction works was undertaken under Contract HK/2012/08 around the monitoring location on  |
|          |           |       |                            |                    |                              |              |             | Remarks / Other Obs: | the monitoring date and no particular observation regarding dust emission was observed during   |
|          |           |       |                            |                    |                              |              |             | Remarks / Other Obs. | sampling periods. Mitigation measure including water spraying for haul road and dusty surface were                                      |
|          |           |       |                            |                    |                              |              |             |                      | generally implmented by the Contractor of HK/2012/08.   |
|          |           |       |                            |                    |                              |              |             |                      | Meanwhile, non WDII-CWB Project construction activities was observed opposite to the monitoring   |
|          |           |       |                            |                    |                              |              |             |                      | station on the monitoring date.   |
|          |           |       |                            |                    |                              |              |             |                      | In view of the above, the exceedance was considered to be not related to the Project works under  |
|          |           |       |                            |                    |                              |              |             |                      | Contract HK/2012/08 and potentially contributed by nearby non WDII-CWB Project constrcution   |
|          |           |       |                            |                    |                              |              |             |                      | activities. Nevertheless, the Contractor of HK/2012/08 was advised to strengthen the overall dust                                       |
|          |           |       |                            |                    |                              |              |             |                      | suppression control measures to ensure all dusty surface and stockpile are covered or dampened to                                       |
|          |           |       |                            |                    |                              |              |             |                      | avoid potential dust emission.  |



| Ref. No. | Date      | Time  | Location                   | Measured TSP Level | Unit                         | Action Level | Limit Level | Follow-up action     |   |
|----------|-----------|-------|----------------------------|--------------------|------------------------------|--------------|-------------|----------------------|---|
| X_18A008 | 29-Oct-18 | 16:50 | CMA5b- Pedestrian<br>Plaza | 442.4              | 1hr TSP (ug/m <sup>3</sup> ) | 332.0        | 500         | Possible reason:     | TSP level potentially in relate to the nearby traffic and ambient condition around the monitoring station<br>at the time of monitoring. |
|          |           |       |                            |                    |                              |              |             | Action taken / to be | Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's                                      |
|          |           |       |                            |                    |                              |              |             | taken:               | working procedures.   |
|          |           |       |                            |                    |                              |              |             |                      | Installation of louver, tiling works and coring works inside building at MVB were undertaken around the                                 |
|          |           |       |                            |                    |                              |              |             | Remarks / Other Obs: | monitoring location under Contract HY/2011/08 on the monitoring date and no particular observation                                      |
|          |           |       |                            |                    |                              |              |             | Remarks / Other Obs. | regarding air quality impact was observed during sampling and mitigation measure including water to                                     |
|          |           |       |                            |                    |                              |              |             |                      | coring works were generally implemented.  |
|          |           |       |                            |                    |                              |              |             |                      | Meanwhile, non WDII-CWB Project construction activities was observed opposite to the monitoring   |
|          |           |       |                            |                    |                              |              |             |                      | station on the monitoring date.   |
|          |           |       |                            |                    |                              |              |             |                      | In view of the above, the exceedance was considered to be not related to the Project works under  |
|          |           |       |                            |                    |                              |              |             |                      | Contract HY/2011/08 and potentially contributed by nearby non WDII-CWB Project constrcution   |
|          |           |       |                            |                    |                              |              |             |                      | activities. Nevertheless, the Contractor of HY/2011/08 was reminded to provided regularly dust  |
|          |           |       |                            |                    |                              |              |             |                      | suppression measures if any potential dust generating operation around the concerned location would                                     |
|          |           |       |                            |                    |                              |              |             |                      | be required to avoid any potential cumulative air quality impact.   |

| Ref. No. | Date      | Time  | Location  | Construction Noise Level, dB(A) | Parameter  | Action Level   | Limit Level dB(A) | Follow-up action            |  |
|----------|-----------|-------|---|---------------------------------|------------|--|-------------------|-----------------------------|--|
| X_18N016 | 22-Nov-18 | 13:25 | M1a-Footbridge at<br>Ex Harbour Road<br>Sports Centre | 77                              | Leq(30min) | when one<br>documented<br>complaint was<br>received. | 75                | Possible reason:            | Breaking works next to the monitoring station under Contractor of HK/2009/02 was observed as the major<br>noise contribution during monitoring.  |
|          |           |       |   |                                 |            |  |                   | Action taken / to be taken: | Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of<br>contractor's working procedure.<br>In view of the current monitoring location was established at the site boundary location as the location was<br>the only available location for representing the WDII project contribution to the nearest NSR (i.e.<br>Causeway Centre), it is considered that the distance attenuation effect shall be taken into account to<br>assess the potential noise impact of the observed construction works under HK/2009/02 to the nearest<br>affected NSR (i.e. Causeway Centre). Based on the distance separation between the measurement point<br>and the observed major noise source (i.e. breaking operation), the SWL of the major noise source was<br>determined to be as 115.1 dB(A). Subsequently, based on the distance attenuation from the noise source<br>to the nearest affected NSR, (i.e. 210.7 m), the <u>construction noise level due to the observed breaking</u><br><u>operation at the nearest sensitive facade is <b>60.6 dB(A)</b>. Hence, it is concluded that the recorded noise<br/>level would not adversely affect the nearest NSR.</u> |
|          |           |       |   |                                 |            |  |                   | Remarks / Other Obs:        | Material handling and breaking works were conducted under Contract HK/2009/02 around the monitoring<br>location during the time of measurement. The breaking works was considered as the major noise<br>contribution during the measurement period and hence the exceedance is considered as Project related.<br>The noise impact to the nearest NSR is further assessed considering the boundary location of the<br>monitoring station and no adverse noise impact to the nearest NSR is identified. Nevertheless, in view of<br>the recorded boundary condition, despite the Contractor of HK/2009/02 deployed noise mitigation<br>measure such as wrapping up the breaker body using acoustic material was observed in place, the<br>Contractor of HK/2009/02 is suggested to adopt additional noise mitigation measures to avoid potential<br>cumulative impact to nearby stakeholders.  |