

Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N194	15-Dec-15	13:27	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement and mitigtaion measures including provision of noise screen and noise barrier was implemented. Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N192	11-Dec-15	10:05	M6 - HK Baptist Church Henrietta Secondary School	68	Leq(30-min)	when one documented complaint was received.	65	Action taken / to be taken: Remarks / Other Obs:	Traffic nearby was observed during monitoring and was considered as the major noise contribution. Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. No construction work was conducted under Contract HY/2009/19 around the concerned location during the time of measurement and it was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N	89 8-Dec-1	16:18	M1a-Habour Road Sports Centre	83	Leq(30-min)	when one documented complaint was received.	75		Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref.	No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_	10N190	8-Dec-15	16:18	M1a-Habour Road Sports Centre	83	Leq(30-min)	when one documented complaint was received.	75		Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
									Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Breaking works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement and mitigtaion measures including provision of noise screen and noise barrier was implemented. Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N186	1-Dec-15	10:20	M1a-Habour Road Sports Centre	89	Leq(30-min)	when one documented complaint was received.	75		Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Bored Pilling works and ground investigation works at portion 2 and reclamation works at WCR3 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N187	1-Dec-15	10:20	M1a-Habour Road Sports Centre	89	Leq(30-min)	when one documented complaint was received.	75		Breaking works at Ex-Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Welding works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N1	7 23-Dec-15	13:42	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75		Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
								Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



R	ef. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
	X_10N198	23-Dec-15	13:42	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
									Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Excavation works was conducted under Contract HK/2009/01 at Area 8 (West of Wan Chai Ferry Pier) during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.



Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
X_10N196	16-Dec-15	9:40	M6 - HK Baptist Church Henrietta Secondary School	69	Leq(30-min)	when one documented complaint was received.	65	Action taken / to be taken: Remarks / Other Obs:	Traffic nearby was observed during monitoring and was considered as the major noise contribution. Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. No construction work was conducted under Contract HY/2009/19 around the concerned location during the time of measurement and it was observed that traffic noise was a major noise source during monitoring. It is concluded that the exceedance was not due to project but to traffic noise nearby.



1	Ref. No.	Date	Time	Location	Construction Noise Level	Unit	Action Level	Limit Level	Follow-up action	
	X_10N193	15-Dec-15	13:27	M1a-Habour Road Sports Centre	84	Leq(30-min)	when one documented complaint was received.	75	Possible reason:	Breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre) under non WDII-CWB Contractor.
									Action taken / to be taken: Remarks / Other Obs:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Bored Pilling works and ground investigation works at portion 5 and backfilling at portion 2 were conducted under Contract HK/2009/02 around the concerned location during the time of measurement while breaking works at Ex- Wan Chai Swimming Pool (adjacent to Habour Road Sports Centre directly opposite to the monitoring station) under non WDII-CWB Contractor was observed as the major noise contribution during monitoring. As such, the exceedance was considered as non-Project related.

Lam Geotechnices Limited

Ref no.	Date	Tidal	Location	Depth	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_10D567	21-Dec-15	Mid-flood	Ex-WPCWA SW	Middle	DO(mg/l)	3.66	3.84	3.73	Possible reason:	Possible in relation to the upstream organic discharge.
									Remarks/ Other Obs:	Repeated the measurement to confirm the result. No odour nuisance was noted during the DO monitoring. Checking with Contractor works and review previous monitoring data. Despite seawall reinstatement was conducted at TPCWAE on the monitoring date, contractor mitigation measures including the use of silt curtain was generally in order while upstream discharge from nearby culvert was noted. In view of the above and no exceedance was recorded on the subsequent monitoring, the exceedance was considered not related to the Project works.

Lam Geotechnices Limited

Define	Data	Tidal	Looption	Parameters (Unit)	Manageman	Action Level	Limait Laval	Follow-up action	1
Ref no.	Date	Tidal	Location	` '					
X_10C705	7-Dec-15	Mid-ebb	P5	DO(mg/l)	5.59	3.36	2.73	Possible reason:	Natural variation or changes of water quality in the vicinity of water abstraction location for the water quality monitoring station.
				Turbidity	19.86	9.10	10.25	Action taken/ to be taken:	Immediate repeated in-situ measurement had conducted to confirm the exceedances. Checking with contractor works and review previous monitoring data.
				ss	19.50	15.00	22.13	Remarks/ Other Obs:	Despite installation of slotted panels was conducted under Contract HK/2012/08 near Zone A2 on the monitoring date, contractor mitigation measures including the use of localized silt curtain was generally in place. In view of no turbidity exceedances were recorded at the monitoring stations located at the immediate downstream location to the construction area and no turbidity exceedance recorded on the subsequent monitoring, it was considered that the turbidity exceedance was not project related. For suspended solid exceedance, in view of no suspended solid exceedance recorded at the monitoring stations located at the immediate downstream location to the construction area and no suspended solid exceedance recorded on the subsequent monitoring, it was considered that suspended solid exceedance was not project related.
X_10C706	26-Dec-15	Mid-ebb	C1	DO(mg/l)	5.59	3.36	2.73	Possible reason:	Natural variation or changes of water quality in the vicinity of water abstraction location for the water quality monitoring station.
				Turbidity	11.37	9.10	10.25	Action taken/ to be taken:	Immediate repeated in-situ measurement had conducted to confirm the exceedances. Checking with contractor works and review previous monitoring data.
				ss	4.50	15.00	22.13	Remarks/ Other Obs:	No marine construction activity was conducted under HK/2009/01 on the monitoring date. No marine construction activity was conducted under HK/2009/02 on the monitoring date, while the location of the construction area was located at downstream of C1 monitoring station. In view of no marine construction activity was conducted and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_W5257	30-Nov-15		RW21-P789	DO(mg/l)	5.81	3.66		Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	11.13	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	8.00	13.00	14.43	Remarks/ Other Obs:	No marine construction activity was conducted under Contract HK/2009/02 on the monitoring date. The installed silt screen was generally in order. In view of the no marine activity conducted and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.
X_W5258	30-Nov-15	Mid-flood	WSD19	DO(mg/l)	5.92	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.56	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				SS	6.00	13.00	14.43	Remarks/ Other Obs:	Despite trimming of grade 400 rock bedding was conducted under Contract HK/2012/08 near Zone A1 on the monitoring date, contractor mitigation measures including the use of localized silt curtain was generally in place. In view of the above and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.
X_W5259	2-Dec-15	Mid-flood	WSD19	DO(mg/l)	4.99	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	9.90	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	9.50	13.00	14.43	Remarks/ Other Obs:	Despite trimming of grade 400 rock bedding was conducted under Contract HK/2012/08 near Zone A1 on the monitoring date, contractor mitigation measures including the use of localized silt curtain was generally in place. In view of the above and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.
X_W5260	7-Dec-15	Mid-flood	WSD19	DO(mg/l)	6.01	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.61	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				SS	9.50	13.00	14.43	Remarks/ Other Obs:	Despite installation of slotted panels was conducted under Contract HK/2012/08 near Zone A2 on the monitoring date, contractor mitigation measures including the use of localized silt curtain was generally in place. In view of the above and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.



Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_W5261	16-Dec-15	Mid-ebb	WSD19	DO(mg/l)	6.15	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	10.23	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	5.50	13.00	14.43	Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. In view of no marine activity conducted, it was considered that the exceedance was not project related.
X_W5262	16-Dec-15	Mid-flood	WSD19	DO(mg/l)	5.07	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.88	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	6.50	13.00	14.43	Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. In view of no marine activity conducted, it was considered that the exceedance was not project related.
X_W5263	18-Dec-15	Mid-ebb	RW21-P789	DO(mg/l)	6.18	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.78	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				SS	4.00	13.00	14.43	Remarks/ Other Obs:	No marine construction activity was conducted under Contract HK/2009/02 on the monitoring date. The installed silt screen was generally in order. In view of the no marine activity conducted and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.
X_W5264	18-Dec-15	Mid-ebb	WSD19	DO(mg/l)	6.96	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	10.51	8.04	9.49	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	6.00	13.00	14.43	Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. In view of no marine activity conducted, it was considered that the exceedance was not project related.

Lam Geotechnices Limited

Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_W5265	18-Dec-15	Mid-flood	WSD19	DO(mg/l)	5.57	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.58	8.04		Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				SS	8.00	13.00	14.43	Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. In view of no marine activity conducted and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.
X_W5266	23-Dec-15	Mid-flood	WSD19	DO(mg/l)	6.39	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	8.24	8.04		Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				SS	6.00	13.00	14.43	Remarks/ Other Obs:	Despite trimming of grade 400 rock mound was conducted under Contract HK/2012/08 near Zone D on the monitoring date, contractor mitigation measures including the use of localized silt curtain was generally in place. In view of the above, it was considered that the exceedance was not project related.
X_W5266	26-Dec-15	Mid-ebb	WSD19	DO(mg/l)	6.44	3.66	3.28	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	14.32	8.04		Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checking with Contractor works and review previous monitoring data.
				ss	8.00	13.00	14.43	Remarks/ Other Obs:	No marine activity was conducted under Contract HK/2012/08 on the monitoring date. In view of no marine activity conducted and no exceedance was recorded on the subsequent monitoring, it was considered that the exceedance was not project related.