

Ref. No.	Date	Time	Location	Measured TSP Level	Unit	Action Level	Limit Level	Follow-up action	
X_18A005	26-May-18	13:00	CMA2a - Causeway Bay Community Centre	433.9	1hr TSP (ug/m <sup>3</sup> )	323.4	500.0	Possible reason:	TSP level potentially in relate to the nearby non WDII-CWB project constrcution works around the monitoring station.
								Action taken / to be	Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's
								taken:	working procedures.
								Remarks / Other Obs:	No construction works was conducted under HY/2009/19 on the monitoring date and no particular observation regarding to air quality impact was observed during sampling Meanwhile, non WDII-CWB Project construction works was observed opposite to the monitoring station.
									In view of the above, the exceedance was considered to be not related to the Project works under Contract HY/2009/19 and potentially contributed by non-WDII-CWB project construction works was observed opposite to the monitoring station. Nevertheless, the Contractor of HY/2009/19 was reminded to provided regularly dust suppression measures if any potential dust generating operation around the concerned location would be required to avoid any potential cumulative air quality impact.



Ref. No.	Date	Time	Location	Measured TSP Level	Unit	Action Level	Limit Level	Follow-up action	
X_18A004	26-May-18	13:00	CMA2a - Causeway Bay Community Centre	433.9	1hr TSP (ug/m <sup>3</sup> )	323.4	500.0	Possible reason:	TSP level potentially in relate to the nearby non WDII-CWB project constrcution works around the monitoring station.
								Action taken / to be	Reviewed the trend of air quality measurement across monitoring stations. Analysis of contractor's
								taken:	working procedures.
									Plastering work, tile fixing work, Green roof installation works and Equipment and System testing
								Remarks / Other Obs:	works was conducted under HY/2011/08 at EVB on the monitoring date and no particular observation regarding to air quality impact was observed during sampling Meanwhile, non WDII-CWB Project construction works was observed opposite to the monitoring station.
									In view of the above, the exceedance was considered to be not related to the Project works under Contract HY/2011/08 and potentially contributed by non-WDII-CWB project construction works was observed opposite to the monitoring station. Nevertheless, the Contractor of HY/2011/08 was reminded to provide regularly dust suppression measures if any potential dust generating operation around the concerned location would be required to avoid any potential cumulative air quality impact.