

Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action	
X_18N011	2-Feb-18	10:00	M1a-Footbridge at Ex Harbour Road Sports Centre	81	Leq(30min)	when one documented complaint was received.	75	Possible reason:	Non WDII-CWB excavation works and hammering immeidately next to the monitoring station was observed as the major noise contribution during monitoring.
								Action taken / to be taken: Remarks / Other Obs:	A repeat measurement was conducted to confirm result and reviewed the trend of previous noise monitoring and Contractor's working procedure. Despite trench excavation work was conducted by Contract HK/2009/02 around the concerned location during the time of measurement, no major noise emanation from the works was observed during monitoring. Meanwhile, excavation works and hammering were conducted under non-WDII-CWB contractor next to the monitoring station and observed as the major noise contribution during monitoring. As such, the exceedance was considered as not relate to Project works under HK/2009/02.



Contract No. HK/2015/01 Wanchai Development Phase II and Central Wanchai Bypass Sampling, Field Measurement and Testing Work (Stage3) Summary for Notification of Exceedance

Ref no.	Date	Tidal	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action	
X_18C002	22-Feb-18	Mid-flood	C7	DO(mg/l)	6.97	3.36	2.73	Possible reason:	Natural variation or changes of water quality in the vicinity of water quality monitoring station.
				Turbidity	27.73	9.10	10.25	Action taken/ to be taken:	Immediate repeated in-situ measurement to confirm the exceedances. Checked with Contractor works and reviewed previous monitoring data.
				SS	34.00	15.00	22.13		No marine construction activity was conducted under Contract HY/2010/08 on the monitoring date and the silt screen installed at for concerned water intake were maintained and generally in order. Hence, it is considered that the exceedance was not related to Project works.